

### 3. SCHEMATIC AND PCB CONNECTION DIAGRAMS

#### WAVEFORMS

Note : The encircled numbers denote measuring points in the schematic diagram.

\*1 50T-JUMP : After switching to the pause mode, press the manual search key.  
 \*2 FOCUS-IN : Press the key without loading a disc.



